

## **Coalite Regeneration Works**

**Period** Monday 08<sup>th</sup> to Sunday 14<sup>th</sup> May 2017

---

### **Main Site Works Undertaken**

- Existing sheeting to ground maintained and repaired as required.
- Re-sheeting of soils in the treatment area
- Water collected on site and placed in bulk tank on site for disposal.
- Slab of old warehouse building punctured to prepare for lifting.
- Area prepared in the treatment area to receive soils by placing base membrane.

### **Monitoring**

- A huge amount of monitoring, continuous and intermittent, is undertaken with many environmental properties being measured and reported every 5 seconds. This is done so that if the site works cause an unacceptable impact immediate action can be taken to address the cause.
- As is to be expected given the low scale of the works being undertaken no significant environmental impacts were detected either on site or off site.

### **Complaints Received**

- No complaints received this week.